Fig. 1

Effect of the amount of active carbon on the time required for transformation




Fig. 2

Effect of the amount of active carbon on the conversion rate to PCA

